


General Information

Date & Time: 05, Feb, 2025 17:19

Make	Toyota	Model	Wigo
YOM	2023	Mileage	4,152
Registration No.	NHC3400	Chassis No.	MHKA4DF5FNJ073037
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Yellow		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.3	106	114	108
2	Boot Lid	109.0	105	110	112
3	Roof	89.3	76	89	94/98
4	Left Front Fender	96.7	95	97	99
5	Left Front Door	92.5	98	94	86
6	Center Panel Left				
7	Left Rear Door	93.3	94	94	92
8	Left Back Panel	92.6	98	96	84
9	Right Front Fender	97.5	101	94	98
10	Right Front Door	96.7	97	100	94
11	Center Panel Right				
12	Right Rear Door	94.5	93	97	94
13	Right Back Panel	101.8	101	99	105

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Minimal / Rear Seat - Grime - Medium / (L) Front Floor Mat - Grime - Small	Remarks Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Mirror - Scratch - Medium / Bonnet, Headlight - Scratch - Small / (L) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Roof - Dent - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes
with warranty booklet and spare tire. without jack and tools. without LTO plate. rust marks at the right side exterior. more scratch at right side mirror.