


General Information

Date & Time: 09, Mar, 2026 13:48

Make	Suzuki	Model	Dzire
YOM	2025	Odo Meter Reading	14,729
Registration No.	ZAD4445	Chassis No.	MBHZF63SXSG567357
CC	1.2	Transmission	A/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.0	110	112	111
2	Boot Lid	89.2	91	89	87
3	Roof	99.7	97	98	107/97
4	Left Front Fender	109.6	107	109	113
5	Left Front Door	105.6	107	107	103
6	Center Panel Left				
7	Left Rear Door	101.8	106	106	94
8	Left Back Panel	101.7	106	108	91
9	Right Front Fender	125.0	119	132	124
10	Right Front Door	144.6	111	115	208
11	Center Panel Right				
12	Right Rear Door	106.3	110	108	101
13	Right Back Panel	109.6	108	106	115

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C		Exterior Evaluation : D	
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain		 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap	
Remarks (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Medium / Rear Seat - Grime - Medium / (R) Rear Trim - Grime - Small / (L) Rear Trim - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Small		Remarks (R) Front Door - Repair Traces - Yes / (L) Rear Door, Molding - Scratch - Medium / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / Roof - Scratch - Small	
Frame Evaluation : A		Functional Evaluation : B	
Remarks Defects not found		Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist	

Inspector Notes

with LTO plate/with spare tire/No spare key/No seat cover/No reverse camera/with warranty booklet/No jack and tools/under engine cover
issue/shift shock