


General Information

Date & Time: 04, Feb, 2025 13:41

Make	Toyota	Model	Land Cruiser
YOM	2022	Mileage	6,310
Registration No.	DAP6887	Chassis No.	JTMAA7BJ1M4007389
CC	3.3	Transmission	A/T
Fuel Type	Diesel	Type of Body	SUV
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	192.0	178	202	196
2	Boot Lid	169.0	145	194	168
3	Roof	157.7	163	159	154/155
4	Left Front Fender	153.3	147	156	157
5	Left Front Door	161.0	155	160	168
6	Center Panel Left				
7	Left Rear Door	163.3	170	157	163
8	Left Back Panel	186.0	196	177	185
9	Right Front Fender	150.6	145	152	155
10	Right Front Door	162.6	163	166	159
11	Center Panel Right				
12	Right Rear Door	159.6	153	161	165
13	Right Back Panel	191.6	185	185	205

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks Bonnet - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
with LTO plate / with warranty booklet/with spare tire/ with tools/ no jack