

General Information

Date & Time: 10, Mar, 2026 15:57

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	26,521
Registration No.	GBF3683	Chassis No.	PA1B18F35R4266453
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	120.0	118	118	124
2	Boot Lid	118.0	114	119	121
3	Roof	106.7	113	102	110/102
4	Left Front Fender	106.3	109	109	101
5	Left Front Door	109.6	108	115	106
6	Center Panel Left				
7	Left Rear Door	112.6	114	114	110
8	Left Back Panel	115.3	125	106	115
9	Right Front Fender	106.8	110	99	111
10	Right Front Door	106.0	103	105	110
11	Center Panel Right				
12	Right Rear Door	107.6	103	109	111
13	Right Back Panel	115.6	113	115	119

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Small / Ceiling - Grime - Small / Mat Other - Grime - Medium / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Worked - Small	Remarks (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Large / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes
Possible flooding. Left signal light at front fender loose. Negative terminal at battery issue. With warranty booklet, spare tire, jack and seat cover. Incomplete tools. 1 key. With LTO PLATE.