

General Information

Date & Time: 05, Feb, 2025 13:50

Make	Toyota	Model	Vios
YOM	2017	Mileage	109,132
Registration No.	NBU9956	Chassis No.	PA1B19F30H4023525
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.6	103	104	110
2	Boot Lid	127.3	124	133	125
3	Roof	113.2	110	114	102/127
4	Left Front Fender	152.0	106	175	175
5	Left Front Door	148.6	154	150	142
6	Center Panel Left				
7	Left Rear Door	170.0	134	177	199
8	Left Back Panel	156.0	188	143	137
9	Right Front Fender	118.3	126	118	111
10	Right Front Door	119.0	121	118	118
11	Center Panel Right				
12	Right Rear Door	118.3	123	118	114
13	Right Back Panel	126.0	125	120	133

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Smell - Yes / Ceiling - Grime - Large / Knobs - Worn, Peel, Crack - Small / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Rear Seat Head Rest - Worn, Peel, Cut - Small / Trunk Room - Worn, Scratch, Cut, Crack - Large	Remarks (L) Rear Door - Repair Traces - Yes / (L) Rear Fender, Molding - Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Large / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Front Fender, Molding - Dent - Large / Bonnet, Headlight - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Large / (L) Front Fender, Molding - Dent - Minimal / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (L) Front Door, Molding - Dent - Minimal / Trunk Hood, Rear Gate - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
with LTO plate number/with spare tire/ No warranty booklet/No jack/No tools /Possible flooding/ rusted seat railings