


General Information

Date & Time: 16, Mar, 2026 14:57

Make	Mitsubishi	Model	Mirage
YOM	2025	Odo Meter Reading	22,700
Registration No.	DBS9170	Chassis No.	PAEA13RJSRA002693
CC	1.2	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	128.6	130	122	134
2	Boot Lid	108.3	104	117	104
3	Roof	101.4	93	112	97/104
4	Left Front Fender	115.0	115	107	123
5	Left Front Door	111.6	114	108	113
6	Center Panel Left				
7	Left Rear Door	107.3	111	104	107
8	Left Back Panel	126.6	132	126	122
9	Right Front Fender	118.0	128	113	113
10	Right Front Door	116.6	121	111	118
11	Center Panel Right				
12	Right Rear Door	111.0	108	109	116
13	Right Back Panel	110.3	108	109	114

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Missing - Yes	Remarks (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Dent - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
With Lto plate, with warranty booklet, 1key, no spare tire, no jack and tools, scratches on headlights and taillights