

General Information

Date & Time: 10, Apr, 2026 10:52

Make	Toyota	Model	Rush
YOM	2020	Odo Meter Reading	130,592
Registration No.	DAN8693-1	Chassis No.	MHKE8FF3PKK015459
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	SUV
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	943.0	1,227	582	1,020
2	Boot Lid	196.0	220	174	194
3	Roof	142.6	86	77	114/294
4	Left Front Fender	786.6	574	898	888
5	Left Front Door	413.0	861	176	202
6	Center Panel Left				
7	Left Rear Door	178.6	189	170	177
8	Left Back Panel	183.0	185	183	181
9	Right Front Fender	356.0	285	455	328
10	Right Front Door	239.3	245	263	210
11	Center Panel Right				
12	Right Rear Door	764.0	228	957	1,107
13	Right Back Panel	188.6	102	227	237

Overall Evaluation :

E

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : E	Exterior Evaluation : E
The diagram shows the interior of a vehicle from a top-down perspective. Inspection points are labeled as follows: A3 at the front seat base, Y3 on both sides of the front seats, Y4 above the front seats, A4 on the side panels behind the front seats, 2 on the dashboard, 4 on the rearview mirror, 5 on the center console, 6 on the side panels behind the rear seats, and 10 on the lower side panels.	The diagram shows the exterior of a vehicle from three perspectives: front, side, and rear. Inspection points are labeled as follows: AU3 on the front hood, Y4 on the front fender, A2 on the front door, A3 on the front bumper, 7 on the front wheel arch, 8 on the front door handle, 9 on the front door hinge, 10 on the front door latch, 1 on the front door trim, 17 on the front door sill, and similar labels for the side and rear views.
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Large / Steering Wheel - Worn, Peel, Crack - Large / (L) Front Trim - Grime - Large / (L) Rear Trim - Grime - Medium / (R) Front Trim - Grime - Medium / (R) Rear Trim - Grime - Medium / Rear Seat - Grime - Medium / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Large / Trunk Room - Worn, Scratch, Cut, Crack - Medium	Remarks (R) Front Door - Repair Traces - Yes / (R) Step - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Step - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / Front Bumper, Grille, Lamps - Crack, Gap - Large / Bonnet, Headlight - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Crack, Gap - Large / (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Large / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Roof - Scratch & Dent - Medium / Front Windshield - Damaged - Large / (L) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch - Small
Frame Evaluation : D	Functional Evaluation : E
Remarks Right Front Pillar - Condition of Welding ? - Yes / Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes / Left Front Pillar - Traces of Bending, or Marks of Panel Repair ? - Yes	Remarks Warning Lamps - Issue - Yes / Power Steering - Issue - Yes / Shift Shock - Function - Weak / Air Conditioner - Function - Weak / Battery - Weak - Yes / Turn Signal, Hazard Flasher - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Seat Belts - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes

with TLO plate/No spare tire/No spare key/glove box issue/fog light issue/plate light issue/front windshield issue/with seat cover/possible flooding/No jack and tools/aircon issue/front bumper partially missing/engine under cover damage/horn issue/unusual soundengine/wiper issue/interior dirty/shift shock/bonnet hood issue/bonnet hood stand issue/hazard issue/seatbelts issue/