

General Information

Date & Time: 20, Apr, 2026 16:21

Make	Ford	Model	Fiesta
YOM	2014	Odo Meter Reading	89,661
Registration No.	RNR693	Chassis No.	MNB8XXARJ8DE20820
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	93.1	100	102	78
2	Boot Lid	82.6	78	71	99
3	Roof	99.8	97	91	104/108
4	Left Front Fender	109.8	119	100	111
5	Left Front Door	95.9	101	93	94
6	Center Panel Left				
7	Left Rear Door	102.5	100	100	108
8	Left Back Panel	186.3	182	198	179
9	Right Front Fender	100.8	112	98	92
10	Right Front Door	129.7	89	86	215
11	Center Panel Right				
12	Right Rear Door	91.6	86	95	94
13	Right Back Panel	103.3	107	103	100

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Steering Wheel - Worn, Peel, Crack - Large / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / Rear Seat - Grime - Small / Sunvisor, Sunglass Holder - Grime - Medium / Ceiling - Grime - Medium / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small	Remarks (R) Front Door - Repair Traces - Yes / (R) Step - Repair Traces - Yes / (R) Step - Replaced - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Step - Replaced - Yes / (L) Rear Fender - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Dent - Small / (L) Front Fender, Molding - Scratch - Medium / (L) Front Door, Molding - Dent - Small / (L) Rear Door, Molding - Dent - Minimal / Trunk Hood, Rear Gate - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small
Frame Evaluation : B	Functional Evaluation : D
Remarks Center Floor Panel - Bulge (Cuts, Major Deforms) or Corrosion ? - Yes	Remarks Air Conditioner - Function - Weak / Battery - Weak - Yes / Brake Pedal - Function - Weak / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
Secondary clutch booster-leaking. No Spare Tire. No Jack and tools. No Seat cover. No Warranty booklet. No Spare key