

General Information

Date & Time: 13, Jul, 2026 15:56

Make	Toyota	Model	Avanza
YOM	2021	Odo Meter Reading	38,296
Registration No.	CBL1947	Chassis No.	MHKM5EF2FLK026698
CC	1.3	Transmission	A/T
Fuel Type	Gas	Type of Body	Wagon
Colour	Gray		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	119.3	122	129	107
2	Boot Lid	108.0	106	115	103
3	Roof	103.7	100	103	110/102
4	Left Front Fender	105.3	105	101	110
5	Left Front Door	102.3	109	101	97
6	Center Panel Left				
7	Left Rear Door	107.3	106	106	110
8	Left Back Panel	94.7	86	89	110
9	Right Front Fender	103.0	105	103	101
10	Right Front Door	105.7	99	110	108
11	Center Panel Right				
12	Right Rear Door	100.8	102	100	101
13	Right Back Panel	92.1	96	96	84

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Inspector Notes
Non moving unit/mileage and functional cannot be determined due to non moving vehicle/electrical issue/with LTO plate/no warranty booklet/no tools and jack/no spare tire/head unit missing/broken taillight/no shift knob/damaged front windshield/left side mirror issue/no spare key