


General Information

Date & Time: 29, Apr, 2026 16:44

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	39,699
Registration No.	EAG2167	Chassis No.	PA1B18F36P4202693
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blackish Red Mica		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.0	119	107	110
2	Boot Lid	96.1	103	85	101
3	Roof	92.6	99	93	87/92
4	Left Front Fender	103.6	101	109	101
5	Left Front Door	100.4	104	99	98
6	Center Panel Left				
7	Left Rear Door	135.6	140	145	122
8	Left Back Panel	108.0	107	112	105
9	Right Front Fender	100.6	102	102	98
10	Right Front Door	100.3	104	96	101
11	Center Panel Right				
12	Right Rear Door	105.7	96	102	119
13	Right Back Panel	103.0	102	103	104

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Medium / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Worked - Small / Carpet - Worked - Minimal / Rear Seat - Grime - Small	Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Front Fender, Molding - Scratch & Dent - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Large / (L) Rear Fender, Molding - Scratch & Dent - Minimal / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Door, Molding - Scratch - Medium / Roof Spoiler, Molding - Scratch - Minimal / Roof - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch & Dent - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
With Lto plate, with warranty booklet and jack, 1key, no spare tire and tools, scratches on headlights and taillights,