

General Information

Date & Time: 29, Apr, 2026 11:13

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	20,118
Registration No.	NJF7726	Chassis No.	PA1B18F37S4293935
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.3	123	113	107
2	Boot Lid	112.3	110	102	125
3	Roof	101.7	103	103	100/101
4	Left Front Fender	104.0	101	104	107
5	Left Front Door	101.2	99	104	101
6	Center Panel Left				
7	Left Rear Door	103.3	101	105	104
8	Left Back Panel	110.6	120	103	109
9	Right Front Fender	112.6	112	112	114
10	Right Front Door	108.6	112	106	108
11	Center Panel Right				
12	Right Rear Door	108.6	110	103	113
13	Right Back Panel	108.3	105	108	112

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Minimal / Mat Other - Grime - Minimal / (R) Front Trim - Grime - Minimal / (R) Front Floor Mat - Worked - Small / (L) Front Floor Mat - Cut, Crack - Medium / Carpet - Worked - Minimal / (L) Front Trim - Grime - Minimal	Remarks (R) Front Fender, Molding - Scratch & Dent - Small / (R) Mirror - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch & Dent - Minimal / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes

Inspector Notes
With Lto plate,with warranty booklet and jack, 2keys, no spare tire and tools, scratches on headlights, battery weak