

General Information

Date & Time: 29, Apr, 2026 11:12

Make	Toyota	Model	Vios
YOM	2026	Odo Meter Reading	6,357
Registration No.	NJK4969	Chassis No.	PA1B18F3X4299728
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	117.6	125	111	117
2	Boot Lid	120.6	116	117	129
3	Roof	104.7	113	103	102/101
4	Left Front Fender	106.3	109	100	110
5	Left Front Door	106.3	110	109	100
6	Center Panel Left				
7	Left Rear Door	106.3	108	107	104
8	Left Back Panel	114.0	122	111	109
9	Right Front Fender	111.3	110	114	110
10	Right Front Door	111.0	108	111	114
11	Center Panel Right				
12	Right Rear Door	110.6	110	107	115
13	Right Back Panel	115.0	106	114	125

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Sunvisor, Sunglass Holder - Grime - Minimal / Overall Interior - Animal Hair - Yes / (L) Front Floor Mat - Worked - Small / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Minimal / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
With Lto plate, with jack and tools, with warranty booklet, 1key, no spare tire, scratches on headlights and taillights