

General Information

Date & Time: 19, Feb, 2025 16:30

Make	Toyota	Model	Supra
YOM	2020	Mileage	6,659
Registration No.	GAV5586	Chassis No.	WZ1DB41000W023908
CC	3.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Coupe
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	131.3	120	141	133
2	Boot Lid				
3	Roof	144.5	144	139	149/146
4	Left Front Fender	102.7	87	103	118
5	Left Front Door	110.3	114	109	108
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	126.6	154	117	109
9	Right Front Fender	110.5	113	122	97
10	Right Front Door	108.7	114	98	114
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	129.3	119	121	148

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Worn - Yes / (R) Front Seat - Worn - Yes / Dashboard - Loose, Deformed - Small	Remarks (L) Rear Fender, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Crack, Gap - Small / (R) Step, In-panel, Side Spoiler - Crack, Gap - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with LTO plate/ with warranty booklet/ no tools and jack/ no spare tire / electrical harness replaced/ service maintenance warning light/ TPMS warning lights