

General Information

Date & Time: 23, May, 2026 19:17

Make	Toyota	Model	Wigo
YOM	2021	Odo Meter Reading	152,582
Registration No.	GAU5096	Chassis No.	MHKA4DF5FLJ048018
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Black		

Body / Panel Condition




#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet				
2	Boot Lid				
3	Roof				
4	Left Front Fender				
5	Left Front Door				
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel				
9	Right Front Fender				
10	Right Front Door				
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel				

Overall Evaluation :

E

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	N / A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain			
Remarks Overall Interior - Smell - Yes / (L) Front Seat - Grime - Large / (R) Front Seat - Grime - Medium / Steering Wheel - Worn, Peel, Crack - Small / Rear Seat - Grime - Small / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Medium		Remarks Defects not found	
Frame Evaluation :	N / A	Functional Evaluation :	N / A
Remarks Defects not found		Remarks Defects not found	

Inspector Notes
With LTO plate, no warranty booklet, no spare key, spare tire unable to verify, unable to open rear door, not starting/non moving vehicle. damaged bumper