

General Information

Date & Time: 17, Feb, 2025 16:57

Make	Toyota	Model	Veloz
YOM	2024	Mileage	18,412
Registration No.	DBN3631	Chassis No.	MHFAB1BY1P3071616
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.3	108	108	109
2	Boot Lid	105.3	104	111	101
3	Roof	120.7	128	130	108/117
4	Left Front Fender	117.3	113	121	118
5	Left Front Door	118.0	111	117	126
6	Center Panel Left				
7	Left Rear Door	115.3	121	109	116
8	Left Back Panel	126.3	143	124	112
9	Right Front Fender	109.6	116	113	100
10	Right Front Door	116.6	121	116	113
11	Center Panel Right				
12	Right Rear Door	116.6	120	111	119
13	Right Back Panel	132.3	123	125	149

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Rear Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

with warranty booklet/ with spare tire/ with jack/ no tools/ with LTO plate / adhesive mark on wind shield