


General Information

Date & Time: 04, May, 2026 19:08

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	25,394
Registration No.	DBP6050	Chassis No.	PA1B18F3XR4264391
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	118.0	130	108	116
2	Boot Lid	121.6	118	122	125
3	Roof	101.9	107	103	97/101
4	Left Front Fender	103.0	100	103	106
5	Left Front Door	112.0	109	113	114
6	Center Panel Left				
7	Left Rear Door	114.3	123	111	109
8	Left Back Panel	124.0	127	126	119
9	Right Front Fender	106.6	109	107	104
10	Right Front Door	110.3	107	111	113
11	Center Panel Right				
12	Right Rear Door	112.0	111	112	113
13	Right Back Panel	113.6	107	109	125

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Mat Other - Grime - Medium / Trunk Room - Loose, Deformed - Medium / (R) Front Trim - Grime - Minimal / (R) Front Floor Mat - Worked - Large / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Cut, Crack - Medium / Carpet - Worked - Minimal	Remarks Bonnet - Repair Traces - Yes / (R) Front Fender, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Minimal / (L) Rear Door, Molding - Scratch & Dent - Minimal / Roof - Scratch & Dent - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Air Conditioner - Function - Weak / Battery - Weak - Yes / Seat Belts - Issue - Yes

Inspector Notes
With Lto plate, with jack and tools, 2keys, no warranty booklet and spare tire, scratches on headlights and taillights, battery weak, aircon issue,