

General Information

Date & Time: 04, May, 2026 19:16

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	45,400
Registration No.	CCF3994	Chassis No.	PA1B18F38R4262901
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blackish Red Mica		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	118.3	120	120	115
2	Boot Lid	124.3	111	139	123
3	Roof	88.3	90	92	80/92
4	Left Front Fender	101.7	104	97	104
5	Left Front Door	103.9	100	105	107
6	Center Panel Left				
7	Left Rear Door	109.6	115	111	103
8	Left Back Panel	101.8	100	110	95
9	Right Front Fender	120.3	128	116	117
10	Right Front Door	127.3	133	123	126
11	Center Panel Right				
12	Right Rear Door	188.3	298	126	141
13	Right Back Panel	152.6	142	152	164

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / Rear Seat - Grime - Medium / (R) Front Trim - Grime - Minimal / (R) Front Seat - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Minimal / Carpet - Worked - Minimal	Remarks (R) Rear Door - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Repair mark - Yes / (R) Rear Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Fender, Molding - Dent - Minimal / Trunk Hood, Rear Gate - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / Roof - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Minimal / Bonnet, Headlight - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

With Lto plate, with warranty booklet and tools, with spare tire and jack, 2keys, scratches on headlights and taillights,