

General Information

Date & Time: 04, May, 2026 18:36

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	14,688
Registration No.	EAJ5249	Chassis No.	PA1B18F35R4268042
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	232.0	237	194	265
2	Boot Lid	133.0	127	127	145
3	Roof	105.7	107	106	102/108
4	Left Front Fender	151.0	164	136	153
5	Left Front Door	118.6	112	113	131
6	Center Panel Left				
7	Left Rear Door	117.0	126	108	117
8	Left Back Panel	130.6	139	134	119
9	Right Front Fender	115.0	114	118	113
10	Right Front Door	162.3	158	168	161
11	Center Panel Right				
12	Right Rear Door	167.3	149	158	195
13	Right Back Panel	119.0	114	124	119

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Room Mirror - Partially Missing - Yes / (R) Front Floor Mat - Worked - Small / Rear Seat - Grime - Minimal / (L) Front Trim - Grime - Minimal / (L) Front Floor Mat - Cut, Crack - Small / Carpet - Worked - Minimal	Remarks Bonnet - Repair Traces - Yes / (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Repair mark - Yes / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / Roof Spoiler, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Crack, Gap - Small / Bonnet, Headlight - Scratch & Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

With Lto plate, with warranty booklet, with jack and tools, 1key, no spare tire, scratches on headlights and taillights, L fender light issue, abnormal sound on engine, issue on room mirror