


General Information

Date & Time: 04, May, 2026 19:22

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	114,489
Registration No.	NHG7322	Chassis No.	PA1B18F3XP4231646
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.0	119	105	112
2	Boot Lid	118.3	114	114	127
3	Roof	97.7	99	99	99/95
4	Left Front Fender	104.0	104	102	106
5	Left Front Door	106.3	104	103	112
6	Center Panel Left				
7	Left Rear Door	110.0	105	108	117
8	Left Back Panel	120.0	125	129	106
9	Right Front Fender	112.3	111	113	113
10	Right Front Door	111.3	112	104	118
11	Center Panel Right				
12	Right Rear Door	112.3	124	102	111
13	Right Back Panel	118.0	104	111	139

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Medium / (R) Front Floor Mat - Grime - Minimal / (R) Front Trim - Grime - Minimal / (R) Front Seat - Grime - Minimal / Mat Other - Grime - Minimal / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Cut, Crack - Medium / Carpet - Worn, Scratch, Cut, Crack - Small / (L) Front Seat - Cigarette Burns - Burnt Minimal	Remarks (R) Front Fender, Molding - Scratch & Dent - Large / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Minimal / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Large / (L) Front Door, Molding - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

With Lto plate, with spare tire and warranty booklet and jack, 3keys, no tools, scratches on headlights and taillights,