

General Information

Date & Time: 05, May, 2026 15:30

Make	Suzuki	Model	S-Presso
YOM	2026	Odo Meter Reading	25,155
Registration No.	FAT8304	Chassis No.	MA3FL61S4TA554903
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	100.1	100	99	101
2	Boot Lid	92.3	98	103	76
3	Roof	105.2	107	113	101/100
4	Left Front Fender	101.4	104	103	97
5	Left Front Door	95.9	94	97	97
6	Center Panel Left				
7	Left Rear Door	95.7	97	90	100
8	Left Back Panel	111.6	117	110	108
9	Right Front Fender	101.0	104	103	96
10	Right Front Door	92.8	94	90	94
11	Center Panel Right				
12	Right Rear Door	89.5	86	90	92
13	Right Back Panel	90.3	78	98	95

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Small / (R) Front Trim - Grime - Small / Rear Seat - Grime - Small	Remarks (R) Rear Door, Molding - Dent - Medium / (R) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

With spare tire. With jack no tools. no seat cover. No warranty booklet