

General Information

Date & Time: 11, May, 2026 15:32

Make	Mitsubishi	Model	L300
YOM	2026	Odo Meter Reading	1,332
Registration No.	NKT6126	Chassis No.	PAEL65NYTSB007595
CC	2.2	Transmission	M/T
Fuel Type	Diesel	Type of Body	FB Body
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	76.6	77	77	75
2	Boot Lid	97.8	104	98	92
3	Roof	67.9	68	68	68/68
4	Left Front Fender	78.6	74	77	85
5	Left Front Door	68.3	69	63	73
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	96.6	99	89	102
9	Right Front Fender	77.2	74	79	79
10	Right Front Door	71.7	75	68	73
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	81.6	84	88	74

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Grime - Small / (L) Front Trim - Grime - Minimal	Remarks (L) Center Panel - Scratch & Dent - Medium / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Side Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Rust, Corrosion - Small / Rear Gate - Scratch - Small / Cargo Bed Floor - Scratch - Small / (R) Side Gate - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / Front Panel - Scratch - Minimal / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

with LTO plate/no warranty booklet/no tools with jack/with spare tire/hairline scratches on the body