


General Information

Date & Time: 20, Sep, 2024 11:35

Make	Toyota	Model	Vios
YOM	2023	Mileage	54,520
Registration No.	NIJ5599	Chassis No.	PA1B18F33P4203784
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	124.0	122	123	127
2	Boot Lid	120.0	111	129	120
3	Roof	109.5	112	106	107/113
4	Left Front Fender	112.3	114	109	114
5	Left Front Door	116.0	117	115	116
6	Center Panel Left				
7	Left Rear Door	116.3	120	111	118
8	Left Back Panel	120.0	130	119	111
9	Right Front Fender	111.6	117	108	110
10	Right Front Door	123.6	119	122	130
11	Center Panel Right				
12	Right Rear Door	124.3	117	129	127
13	Right Back Panel	115.6	109	120	118

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Trunk Room - Worn, Scratch, Cut, Crack - Medium	Remarks Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Trunk Hood, Rear Gate - Dent - Medium / (R) Rear Door, Molding - Scratch & Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
has hairline scratchers/ no reverse camera/ tires needs to be inflated to spec