

General Information

Date & Time: 08, May, 2026 15:46

Make	Toyota	Model	Raize
YOM	2025	Odo Meter Reading	14,913
Registration No.	DBR2338	Chassis No.	MHKAB1BA0RJ099376
CC	1.2	Transmission	M/T
Fuel Type	Gas	Type of Body	SUV
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.0	101	104	110
2	Boot Lid	75.3	72	82	73
3	Roof	90.5	88	91	93/90
4	Left Front Fender	83.2	80	88	82
5	Left Front Door	89.8	85	97	88
6	Center Panel Left				
7	Left Rear Door	89.0	92	90	85
8	Left Back Panel	84.2	80	84	89
9	Right Front Fender	76.5	73	82	75
10	Right Front Door	85.5	84	93	80
11	Center Panel Right				
12	Right Rear Door	84.6	82	86	86
13	Right Back Panel	77.3	86	73	74

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Minimal / (L) Front Floor Mat - Grime - Minimal	Remarks (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
with LTO plate/with warranty booklet/incomplete tools with jack/with spare tire/hairline scratches on the body