

General Information

Date & Time: 14, May, 2026 07:34

Make	Toyota	Model	Avanza
YOM	2025	Odo Meter Reading	50,832
Registration No.	BAH6153	Chassis No.	MHFAA1BY8S0044913
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.6	118	110	119
2	Boot Lid	112.0	105	104	127
3	Roof	121.2	127	135	108/115
4	Left Front Fender	106.6	108	109	103
5	Left Front Door	122.6	115	127	126
6	Center Panel Left				
7	Left Rear Door	114.0	114	111	117
8	Left Back Panel	135.0	139	116	150
9	Right Front Fender	103.4	111	98	101
10	Right Front Door	201.0	215	201	187
11	Center Panel Right				
12	Right Rear Door	112.3	116	103	118
13	Right Back Panel	111.3	113	113	108

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Small / (R) Front Seat - Grime - Small / (L) Front Seat - Worn - Yes / Ceiling - Crinkle - Small / Rear Seat - Grime - Small / Trunk Room - Loose, Deformed - Medium	Remarks (R) Front Door - Repair Traces - Yes / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Crack, Gap - Medium / Bonnet, Headlight - Scratch & Dent - Medium / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes

with warranty booklet, no jack and tools, no spare tire, with LTO plate, scratches on tail light, plate light issue, trunk room partially missing