

General Information

Date & Time: 18, Feb, 2025 16:35

Make	Suzuki	Model	Dzire
YOM	2024	Mileage	17,880
Registration No.	NFS4150	Chassis No.	MBHZF63S5RG467841
CC	1.2	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.3	100	102	105
2	Boot Lid	87.8	90	84	89
3	Roof	105.1	98	100	113/110
4	Left Front Fender	100.6	90	105	107
5	Left Front Door	98.3	110	91	94
6	Center Panel Left				
7	Left Rear Door	89.3	94	89	86
8	Left Back Panel	89.5	95	92	82
9	Right Front Fender	103.1	102	110	98
10	Right Front Door	104.3	100	108	105
11	Center Panel Right				
12	Right Rear Door	104.7	120	92	102
13	Right Back Panel	100.2	94	97	110

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Medium	Remarks (R) Front Fender, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Minimal / (L) Front Fender, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet, no jack, no tools, with spare tire, no LTO plate, no reverse camera, front right fog light issue