

General Information

Date & Time: 18, Feb, 2025 10:15

Make	Toyota	Model	Vios
YOM	2024	Mileage	18,370
Registration No.	NHM8539	Chassis No.	PA1B18F35R4244100
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.6	121	111	118
2	Boot Lid	126.3	123	132	124
3	Roof	107.7	108	107	103/113
4	Left Front Fender	101.8	105	102	99
5	Left Front Door	100.3	103	100	98
6	Center Panel Left				
7	Left Rear Door	95.0	98	95	93
8	Left Back Panel	106.3	109	106	104
9	Right Front Fender	116.0	116	115	117
10	Right Front Door	110.0	108	111	111
11	Center Panel Right				
12	Right Rear Door	109.6	109	107	113
13	Right Back Panel	116.3	116	111	122

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Grime - Medium / (L) Front Floor Mat - Cut, Crack - Medium	Remarks Front Bumper, Grille, Lamps - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Head Light, High Beam - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes

with tools and jack/ with spare tire/ with warranty booklet/ no hi beam/ reverse camera issue