

General Information

Date & Time: 22, May, 2026 07:40

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	33,368
Registration No.	NKS6478	Chassis No.	PAHACACA4S6426088
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.0	101	107	104
2	Boot Lid	86.0	71	129	58
3	Roof	111.7	117	114	109/107
4	Left Front Fender	105.3	105	108	103
5	Left Front Door	105.6	108	107	102
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	58.3	57	60	58
9	Right Front Fender	102.9	104	106	99
10	Right Front Door	103.6	101	106	104
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	64.6	58	69	67

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Minimal / Dashboard - Traces of Adhesive Tape - Yes / Dashboard - Loose, Deformed - Small / Carpet - Worn, Scratch, Cut, Crack - Small / (R) Front Floor Mat - Worked - Small / (L) Front Seat - Grime - Minimal / (R) Front Seat - Grime - Minimal / Rear Seat - Grime - Minimal / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal / Console, Switchs, Vents - Worked - Minimal	Remarks (R) Front Door - Repair Traces - Yes / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Guard Frame - Modified - Large / (R) Side Gate - Scratch - Large / Rear Gate - Modified - Medium / (L) Side Gate - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / Roof - Scratch - Minimal / Cargo Bed Floor - Scratch & Dent - Medium / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Crack, Gap - Medium / (R) Mirror - Scratch - Small / (L) Mirror - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
with Ito plate/with warranty booklet/with tools and jack/with spare tire/without reverse camera/gas cap damage/without spare key