

General Information

Date & Time: 23, May, 2026 08:24

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	11,359
Registration No.	NHS2277	Chassis No.	PA1B18F32R4259220
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	169.3	173	168	167
2	Boot Lid	169.3	172	157	179
3	Roof	162.0	169	164	150/165
4	Left Front Fender	166.3	164	165	170
5	Left Front Door	146.6	153	146	141
6	Center Panel Left				
7	Left Rear Door	167.6	174	162	167
8	Left Back Panel	185.6	195	197	165
9	Right Front Fender	162.0	167	159	160
10	Right Front Door	154.3	156	143	164
11	Center Panel Right				
12	Right Rear Door	157.3	151	152	169
13	Right Back Panel	165.6	163	161	173

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (L) Front Seat - Worn - Yes / (R) Front Seat - Grime - Small / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal / (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / Rear Seat - Grime - Small	Remarks (L) Rear Fender - Repair Traces - Yes / Overall Exterior - Faded(Color, Gloss) - Yes / Overall Exterior - Full Re-Paint in same color - Yes / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Dent - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

with warranty booklet, no jack and tools, with spare tire, with LTO plate, scratches on tail, all floormat missing