

General Information

Date & Time: 25, May, 2026 12:26

Make	Toyota	Model	Vios
YOM	2019	Odo Meter Reading	100,336
Registration No.	NEI2464	Chassis No.	PA1B18F33K4082329
CC	1.3	Transmission	A/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	178.3	163	204	168
2	Boot Lid	164.3	175	158	160
3	Roof	88.7	98	84	91/83
4	Left Front Fender	162.6	89	175	224
5	Left Front Door	132.9	92	100	207
6	Center Panel Left				
7	Left Rear Door	144.2	84	176	173
8	Left Back Panel	145.5	84	164	189
9	Right Front Fender	140.3	141	125	155
10	Right Front Door	141.6	136	133	156
11	Center Panel Right				
12	Right Rear Door	293.0	410	267	202
13	Right Back Panel	158.3	151	138	186

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : D	Exterior Evaluation : D
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Medium / (L) Front Floor Mat - Worked - Large / (R) Front Seat - Cut, Crack - Large / (L) Front Trim - Grime - Medium / Trim Other - Loose, Deformed - Medium / (R) Front Trim - Grime - Medium / Rear Seat - Grime - Small / (L) Front Seat - Grime - Minimal / Glove Box - Loose, Deformed - Small / Console, Switches, Vents - Loose, Deformed - Small / Dashboard - Traces of Adhesive Tape - Yes	Remarks Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / (R) Front Door, Molding - Scratch & Dent - Small / (R) Mirror - Faded(Color, Gloss) - Yes / (R) Rear Door, Molding - Dent - Small / (R) Rear Fender, Molding - Dent - Small / Trunk Hood, Rear Gate - Modified - Large / (L) Rear Fender, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Fender, Molding - Dent - Medium / Front Bumper, Grille, Lamps - Crack, Gap - Medium / Bonnet, Headlight - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
with lto plate/with spare tire/no tools and jack/with reverse camera/with hairlines scratches on the body/glove box issue/headlight damage