

General Information

Date & Time: 23, May, 2026 18:38

Make	Toyota	Model	Wigo
YOM	2025	Odo Meter Reading	22,305
Registration No.	CCP1336	Chassis No.	MHKAA1BC1RJ033018
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Orange		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	128.6	136	122	128
2	Boot Lid	110.0	112	108	110
3	Roof	112.0	119	112	110/107
4	Left Front Fender	108.0	114	108	102
5	Left Front Door	122.6	127	117	124
6	Center Panel Left				
7	Left Rear Door	121.3	127	117	120
8	Left Back Panel	107.3	109	108	105
9	Right Front Fender	106.0	103	110	105
10	Right Front Door	122.3	121	115	131
11	Center Panel Right				
12	Right Rear Door	120.6	122	111	129
13	Right Back Panel	113.6	115	111	115

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Small / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Minimal	Remarks (R) Rear Door, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

no tools/ with jack and spare tire/ with LTO plate and warranty booklet/ 2 keys/ light scratches around the exterior/