

General Information

Date & Time: 25, May, 2026 17:21

Make	Toyota	Model	Hilux Tamaraw
YOM	2026	Odo Meter Reading	14,761
Registration No.	NLC4751	Chassis No.	PAHACACA7S6431060
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.3	109	118	107
2	Boot Lid	58.3	63	56	56
3	Roof	128.0	142	126	117/127
4	Left Front Fender	119.3	117	113	128
5	Left Front Door	116.3	120	115	114
6	Center Panel Left	112.6	127	108	103
7	Left Rear Door				
8	Left Back Panel	59.6	61	58	60
9	Right Front Fender	110.0	116	108	106
10	Right Front Door	112.3	111	112	114
11	Center Panel Right	111.3	122	107	105
12	Right Rear Door				
13	Right Back Panel	69.3	64	72	73

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Grime - Large / Ceiling - Grime - Minimal / (R) Front Trim - Grime - Minimal / (R) Front Floor Mat - Grime - Minimal / Carpet - Worked - Minimal	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Side Gate - Scratch - Small / Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Cargo Bed Floor - Scratch - Large / (L) Side Gate - Scratch - Medium / Roof - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
No Lto plate, with spare tire and jack, 1key, no warranty booklet and tools, scratches on headlights