

General Information

Date & Time: 25, May, 2026 17:47

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	25,561
Registration No.	NLA3024	Chassis No.	PAHACACA3S6421559
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Dropside
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.1	100	107	99
2	Boot Lid	56.1	49	46	73
3	Roof	108.7	111	116	106/102
4	Left Front Fender	104.0	103	106	103
5	Left Front Door	110.6	117	108	107
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	82.8	90	75	84
9	Right Front Fender	102.1	107	101	99
10	Right Front Door	102.0	100	106	100
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	60.0	55	64	61

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (L) Front Fender - Repair Traces - Yes / Bonnet, Headlight - Dent - Medium / (L) Front Fender, Molding - Dent - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (L) Side Gate - Scratch - Medium / (L) Guard Frame - Scratch - Medium / Rear Gate - Scratch - Large / Cargo Bed Floor - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Crack, Gap - Medium / (R) Side Gate - Scratch - Medium / (R) Front Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Lamps (Brake, Tail, Fog) - Issue - Yes

Inspector Notes

no jack and tool/ no spare tire/ light scratches around the exterior/ dome light issue/tail light issue/ with LTO plate and warranty booklet/ 2 keys