

General Information

Date & Time: 25, May, 2026 17:08

Make	Toyota	Model	Hilux Tamaraw
YOM	2026	Odo Meter Reading	20,660
Registration No.	DCC8413	Chassis No.	PAHACACA4S6428424
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.0	110	107	104
2	Boot Lid	53.5	57	49	55
3	Roof	127.2	129	131	132/117
4	Left Front Fender	109.3	112	112	104
5	Left Front Door	113.3	110	112	118
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	57.8	53	59	61
9	Right Front Fender	109.6	110	113	106
10	Right Front Door	114.0	112	118	112
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	59.5	56	65	58

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks Front Bumper, Grille, Lamps - Scratch - Medium / Cargo Bed Floor - Scratch & Dent - Large / Rear Gate - Dent - Small / (R) Side Gate - Dent - Small / (L) Side Gate - Dent - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

no tools/ light scratches around the exterior/ with jack and spare tire/ with warranty booklet and LTO plate/ 4 keys