

General Information

Date & Time: 25, May, 2026 20:28

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	8,683
Registration No.	ZAD4903	Chassis No.	PA1B18F32R4272338
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	121.3	129	113	122
2	Boot Lid	124.3	118	128	127
3	Roof	112.5	119	113	108/110
4	Left Front Fender	110.6	112	111	109
5	Left Front Door	117.0	115	114	122
6	Center Panel Left				
7	Left Rear Door	114.6	121	115	108
8	Left Back Panel	126.3	135	118	126
9	Right Front Fender	113.6	114	119	108
10	Right Front Door	106.0	107	105	106
11	Center Panel Right				
12	Right Rear Door	116.6	106	117	127
13	Right Back Panel	123.6	125	116	130

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Minimal / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal / (L) Front Seat - Grime - Minimal	Remarks (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Fender, Molding - Rust, Corrosion - Minimal / (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Rust, Corrosion - Medium / (L) Rear Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
With LTO plate, with warranty booklet, with tools, with jack, with warning device, with hairline scratches, with spare tire, with spare key 2pcs.