


General Information

Date & Time: 23, Sep, 2024 13:26

Make	Toyota	Model	Vios
YOM	2024	Mileage	12,754
Registration No.	NHR5402	Chassis No.	PA1B18F31P4231387
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Others		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	124.0	125	122	125
2	Boot Lid	120.6	117	112	133
3	Roof	119.7	118	111	128/122
4	Left Front Fender	113.0	116	112	111
5	Left Front Door	114.3	115	112	116
6	Center Panel Left				
7	Left Rear Door	119.0	122	125	110
8	Left Back Panel	116.3	122	114	113
9	Right Front Fender	125.6	132	121	124
10	Right Front Door	123.0	137	114	118
11	Center Panel Right				
12	Right Rear Door	121.0	111	123	129
13	Right Back Panel	119.3	114	114	130

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks Roof - Dent - Minimal / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Fender, Molding - Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

minimal hairline scratches/ good condition