

General Information

Date & Time: 01, Jun, 2026 15:24

Make	Toyota	Model	Lite Ace
YOM	2024	Odo Meter Reading	7,573
Registration No.	GBC3027	Chassis No.	MHKB3FE10PK003071
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Utility Cargo
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	58.6	63	54	58
2	Boot Lid	53.2	50	57	53
3	Roof	54.4	58	53	55/52
4	Left Front Fender	60.7	53	57	72
5	Left Front Door	50.3	49	50	52
6	Center Panel Left				
7	Left Rear Door	52.7	53	54	51
8	Left Back Panel	55.4	52	57	58
9	Right Front Fender	56.9	66	54	51
10	Right Front Door	48.5	48	49	49
11	Center Panel Right				
12	Right Rear Door	57.2	59	60	53
13	Right Back Panel	62.4	57	63	68

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Animal Hair - Yes / Ceiling - Grime - Medium / (L) Front Seat - Grime - Minimal / (R) Front Seat - Grime - Small / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Grime - Small	Remarks (L) Mirror - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Large / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

Left side rear light crack. With warranty booklet, tools, jack, seatcover, sparetire, LTO plate and 2keys.