

General Information

Date & Time: 26, Feb, 2025 13:45

Make	Toyota	Model	Hilux
YOM	2020	Mileage	65,690
Registration No.	NGO3258	Chassis No.	MR0HA3CD2L0450044
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.0	108	105	102
2	Boot Lid	92.0	96	88	92
3	Roof	97.3	100	98	93/99
4	Left Front Fender	92.8	94	89	95
5	Left Front Door	92.1	93	93	90
6	Center Panel Left				
7	Left Rear Door	94.2	103	87	93
8	Left Back Panel	126.3	89	166	124
9	Right Front Fender	95.2	86	100	100
10	Right Front Door	90.3	93	91	87
11	Center Panel Right				
12	Right Rear Door	91.8	88	91	97
13	Right Back Panel	110.0	110	104	116

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / (R) Front Trim - Grime - Medium / (L) Front Trim - Grime - Small / Carpet - Worn, Scratch, Cut, Crack - Small / Dashboard - Worn, Scratch, Cut, Crack - Large	Remarks (L) Rear Corner Panel - Repair Traces - Yes / (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Dent - Medium / (R) Rear Door, Molding - Dent - Small / (R) Side Gate - Repair mark - Yes / Rear Gate - Repair mark - Yes / Rear Gate - Dent - Small / (L) Side Gate - Repair mark - Yes / Rear Bumper, Lamps, Panels - Dent - Medium / (L) Front Door, Molding - Repair mark - Yes / (L) Front Door, Molding - Scratch & Dent - Small / (L) Front Fender, Molding - Dent - Medium / Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Side Gate - Scratch - Small / Bonnet, Headlight - Scratch - Large / Roof - Scratch - Large / (R) Side Gate - Scratch - Large / (L) Step, In-panel, Side Spoiler - Scratch - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Mirror - Crack - Cracks / (L) Mirror - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Mirror - Scratch - Small / Front Windshield - Scratch, Stone chip - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Remote Key & Smart entry - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

with warranty booklet, with jack and tools, with spare tire, no LTO plate, smart key issue