

General Information

Date & Time: 22, Feb, 2025 15:39

Make	Toyota	Model	Vios
YOM	2024	Mileage	21,447
Registration No.	DBJ9644	Chassis No.	PA1B18F35P4227827
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.6	101	104	112
2	Boot Lid	112.0	106	120	110
3	Roof	100.8	102	115	91/95
4	Left Front Fender	99.1	99	100	99
5	Left Front Door	101.8	99	104	103
6	Center Panel Left				
7	Left Rear Door	109.0	112	106	109
8	Left Back Panel	111.6	128	105	102
9	Right Front Fender	100.3	105	95	101
10	Right Front Door	100.3	97	100	104
11	Center Panel Right				
12	Right Rear Door	99.5	99	95	104
13	Right Back Panel	101.8	100	97	109

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes / Trunk Room - Worn, Scratch, Cut, Crack - Small	Remarks Roof - Dent - Minimal / Rear Bumper, Lamps, Panels - Dent - Minimal / (L) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Crack, Gap - Large / (R) Rear Door, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
with LTO plate/with spare tire/jack and incomplete tools/without warranty booklet/No reverse camera