

General Information

Date & Time: 19, Jun, 2026 16:05

Make	Nissan	Model	NV350
YOM	2020	Odo Meter Reading	116,373
Registration No.	NAN1595	Chassis No.	JN1TC2E26Z0063040
CC	2.5	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.0	109	108	125
2	Boot Lid	102.2	99	110	98
3	Roof	115.0	123	123	107/107
4	Left Front Fender	113.0	102	123	114
5	Left Front Door	121.6	110	128	127
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	116.0	120	118	110
9	Right Front Fender	118.6	117	122	117
10	Right Front Door	108.0	108	101	115
11	Center Panel Right	112.0	122	116	98
12	Right Rear Door	98.1	88	101	105
13	Right Back Panel	115.3	114	107	125

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Large / Room Lamp - Partially Missing - Yes / Mat Other - Grime - Large / (R) Front Trim - Grime - Medium / Trim Other - Worked - Small / Rear Seat - Grime - Small / (L) Front Trim - Grime - Medium	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Small / (R) Center Panel - Scratch & Dent - Minimal / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch & Dent - Large / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Roof - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Large / Front Panel - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Crack, Gap - Medium
Frame Evaluation : A	Functional Evaluation : D
Remarks Defects not found	Remarks Power Window (each) - Stuck, Gap - Yes / Air Conditioner - Function - Weak / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

With Lto plate, with spare tire, 1key, no warranty booklet and jack and tools, scratches on headlights, Crack taillight, aircon issue, plate light issue, Worn rear tires