

General Information

Date & Time: 22, Feb, 2025 15:34

Make	Toyota	Model	Vios
YOM	2023	Mileage	19,047
Registration No.	DBI6832	Chassis No.	PA1B18F3XP4213647
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.3	108	104	113
2	Boot Lid	101.6	94	102	109
3	Roof	99.4	102	97	102/97
4	Left Front Fender	90.8	93	89	90
5	Left Front Door	93.8	97	95	90
6	Center Panel Left				
7	Left Rear Door	89.7	94	87	88
8	Left Back Panel	102.6	101	103	104
9	Right Front Fender	89.4	89	88	92
10	Right Front Door	94.6	97	96	91
11	Center Panel Right				
12	Right Rear Door	99.8	95	97	107
13	Right Back Panel	101.0	101	100	102

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Small / Rear Seat - Grime - Medium / (L) Front Floor Mat - Grime - Medium / (L) Front Seat - Grime - Small	Remarks (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
With warranty booklet, spare tire, jack and tools. with LTO plate.