

General Information

Date & Time: 10, Jun, 2026 14:58

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	41,351
Registration No.	FAQ3110	Chassis No.	PA1B18F37P4228008
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	86.8	82	93	85
2	Boot Lid	85.6	84	83	90
3	Roof	81.7	82	85	82/78
4	Left Front Fender	136.6	137	137	136
5	Left Front Door	121.0	117	123	123
6	Center Panel Left				
7	Left Rear Door	78.1	74	80	80
8	Left Back Panel	99.4	112	95	91
9	Right Front Fender	85.3	84	82	90
10	Right Front Door	88.4	93	85	88
11	Center Panel Right				
12	Right Rear Door	89.4	84	87	97
13	Right Back Panel	91.3	95	83	97

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Minimal / (L) Front Seat - Grime - Minimal / Rear Seat - Grime - Small / (R) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Grime - Small / Ceiling - Grime - Minimal / (L) Front Trim - Grime - Small	Remarks (L) Front Fender, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Crack, Gap - Medium / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

with LTO plate/no warranty booklet/with incomplete tools with jack/with spare tire/air recirculating button issue/headlight cover cracked/hairline scratches on the body