

General Information

Date & Time: 11, Jun, 2026 09:24

Make	Toyota	Model	Avanza
YOM	2025	Odo Meter Reading	33,915
Registration No.	FAS4138	Chassis No.	MHFAA1BY7R0034500
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	87.3	83	93	86
2	Boot Lid	81.8	83	84	79
3	Roof	97.4	106	104	93/87
4	Left Front Fender	87.4	86	90	86
5	Left Front Door	93.0	92	93	94
6	Center Panel Left				
7	Left Rear Door	91.8	93	90	93
8	Left Back Panel	100.6	111	103	88
9	Right Front Fender	86.6	87	88	85
10	Right Front Door	92.7	93	94	92
11	Center Panel Right				
12	Right Rear Door	91.4	94	89	91
13	Right Back Panel	105.3	102	103	111

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Seat - Grime - Minimal / Rear Seat - Grime - Minimal / (L) Front Seat - Grime - Minimal / (L) Front Floor Mat - Grime - Small / Overall Interior - Smell - Yes	Remarks (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch & Dent - Small / (L) Mirror - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Small / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
with Ito plate, with warranty booklet, no spare key, incomplete tools with jack, with spare tire, maintenance warning lamp on , overall hairline scratches on the body