

General Information

Date & Time: 25, Feb, 2025 08:53

Make	Toyota	Model	Vios
YOM	2022	Mileage	59,658
Registration No.	EAE6648	Chassis No.	PA1B18F35M4167687
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	118.6	111	122	123
2	Boot Lid	102.5	99	103	106
3	Roof	98.3	102	95	99/98
4	Left Front Fender	99.8	93	102	105
5	Left Front Door	104.0	106	105	101
6	Center Panel Left				
7	Left Rear Door	107.6	105	108	110
8	Left Back Panel	115.6	123	120	104
9	Right Front Fender	99.4	107	97	95
10	Right Front Door	101.0	96	101	106
11	Center Panel Right				
12	Right Rear Door	94.8	95	92	98
13	Right Back Panel	98.3	94	90	111

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Grime - Small / Rear Seat - Grime - Large / (R) Front Seat - Grime - Medium	Remarks (L) Front Door, Molding - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Front Fender, Molding - Dent - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Front Fender, Molding - Dent - Minimal / (L) Rear Door, Molding - Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
with LTO plate/with spare tire/with jack /No tools and warranty booklet/right side mirror damage