

General Information

Date & Time: 11, Jun, 2026 08:41

Make	MG	Model	MG 5
YOM	2026	Odo Meter Reading	1,852
Registration No.	GB07602	Chassis No.	LSJA36E35SZ186178
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	138.3	147	128	140
2	Boot Lid	145.0	129	164	142
3	Roof	132.0	134	137	127/130
4	Left Front Fender	133.6	136	136	129
5	Left Front Door	135.6	137	130	140
6	Center Panel Left				
7	Left Rear Door	135.3	129	136	141
8	Left Back Panel	147.0	144	150	147
9	Right Front Fender	130.6	128	130	134
10	Right Front Door	131.0	132	123	138
11	Center Panel Right				
12	Right Rear Door	129.3	123	133	132
13	Right Back Panel	141.0	135	142	146

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / (L) Front Seat - Grime - Minimal / (R) Front Seat - Grime - Minimal / (R) Front Trim - Grime - Minimal / Rear Seat - Grime - Small / (R) Rear Trim - Grime - Minimal / (L) Front Trim - Grime - Small / (L) Rear Trim - Grime - Minimal / Overall Interior - Animal Hair - Yes	Remarks Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Medium / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
Left side Reverse light busted. Without seatcover, Warranty booklet, LTO plate. With jack, sparetire, tools and 1key.