

General Information

Date & Time: 22, Feb, 2025 14:45

Make	Toyota	Model	Vios
YOM	2024	Mileage	23,337
Registration No.	NHR8272	Chassis No.	PA1B18F34P4234669
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.8	107	98	104
2	Boot Lid	99.1	100	100	97
3	Roof	98.5	102	100	94/99
4	Left Front Fender	92.5	98	89	91
5	Left Front Door	95.8	96	92	100
6	Center Panel Left				
7	Left Rear Door	101.7	99	110	96
8	Left Back Panel	104.7	108	111	95
9	Right Front Fender	103.0	104	105	100
10	Right Front Door	101.0	107	101	95
11	Center Panel Right				
12	Right Rear Door	98.2	97	102	96
13	Right Back Panel	99.7	98	90	111

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Mat Other - Grime - Medium / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Large / (L) Front Seat - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes / (R) Front Trim - Grime - Minimal	Remarks (R) Front Fender, Molding - Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Rear Door, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with warranty booklet, with jack and incomplete tools, with spare tire, with LTO plate