


General Information

Date & Time: 22, Feb, 2025 14:46

Make	Toyota	Model	Vios
YOM	2024	Mileage	19,705
Registration No.	DBM6539	Chassis No.	PA1B18F38R4244902
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.9	112	96	101
2	Boot Lid	97.7	98	95	100
3	Roof	97.1	94	103	89/102
4	Left Front Fender	90.3	89	91	91
5	Left Front Door	90.3	91	93	87
6	Center Panel Left				
7	Left Rear Door	93.5	94	93	94
8	Left Back Panel	98.3	101	98	97
9	Right Front Fender	87.8	87	89	88
10	Right Front Door	93.0	94	95	90
11	Center Panel Right				
12	Right Rear Door	101.8	97	107	102
13	Right Back Panel	93.0	95	93	91

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Rear Trim - Grime - Medium / (R) Front Seat - Grime - Small / Rear Seat - Grime - Medium / (L) Front Floor Mat - Grime - Medium	Remarks (R) Front Door, Molding - Scratch & Dent - Small / Bonnet, Headlight - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
without warranty booklet and spare tire. with Jack but incomplete tools. with LTO plate.