

General Information

Date & Time: 22, Feb, 2025 14:37

Make	Toyota	Model	Vios
YOM	2024	Mileage	18,943
Registration No.	NFR7855	Chassis No.	PA1B18F33R4255757
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.3	111	109	117
2	Boot Lid	110.0	120	103	107
3	Roof	114.2	114	104	109/130
4	Left Front Fender	102.0	99	100	107
5	Left Front Door	101.8	101	99	105
6	Center Panel Left				
7	Left Rear Door	112.9	129	110	100
8	Left Back Panel	116.0	125	116	107
9	Right Front Fender	107.6	120	101	102
10	Right Front Door	96.9	96	96	100
11	Center Panel Right				
12	Right Rear Door	110.3	100	116	115
13	Right Back Panel	116.3	106	111	132

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes / (L) Front Floor Mat - Grime - Medium	Remarks Trunk Hood, Rear Gate - Dent - Minimal / (R) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Small / (R) Mirror - Scratch, Peeled - Minimal / (L) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

with LTO plate/with spare tire/jack and tools with warranty booklet/front bumper was re-painted