

General Information

Date & Time: 16, Jun, 2026 16:47

Make	Toyota	Model	Avanza
YOM	2025	Odo Meter Reading	29,029
Registration No.	GBK6999	Chassis No.	MHFAA1BY3S0041899
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	MPV
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	117.0	112	115	124
2	Boot Lid	106.0	105	110	103
3	Roof	105.0	101	106	105/108
4	Left Front Fender	102.3	105	101	101
5	Left Front Door	110.0	107	107	116
6	Center Panel Left				
7	Left Rear Door	109.3	108	107	113
8	Left Back Panel	121.3	127	125	112
9	Right Front Fender	102.2	104	104	99
10	Right Front Door	108.6	113	106	107
11	Center Panel Right				
12	Right Rear Door	107.3	108	107	107
13	Right Back Panel	124.0	113	128	131

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Grime - Minimal / (R) Front Trim - Grime - Minimal / (R) Front Seat - Grime - Minimal / Overall Interior - Animal Hair - Yes / Ceiling - Grime - Small / Rear Seat - Grime - Small / (R) Rear Trim - Grime - Minimal / (L) Rear Trim - Grime - Minimal / (L) Front Trim - Grime - Minimal / (L) Front Seat - Grime - Minimal	Remarks Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Mirror - Scratch - Medium / (R) Front Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch - Large / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Mirror - Scratch - Medium / (R) Front Fender, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Warning Lamps - Issue - Yes / Door Lock - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
Maintenance warning lamp on. Left rear door lock issue. Without jack, tools, warrantybooklet. With seatcover, sparetire, LTO plate and 1key.