

General Information

Date & Time: 16, Jun, 2026 12:39

Make	Toyota	Model	Raize
YOM	2023	Odo Meter Reading	1
Registration No.	GBA3348	Chassis No.	MHKAB1BA5PJ060117
CC	1.2	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	119.6	119	128	112
2	Boot Lid	111.0	109	113	111
3	Roof	115.5	107	114	115/126
4	Left Front Fender	103.8	108	112	92
5	Left Front Door	122.3	125	125	117
6	Center Panel Left				
7	Left Rear Door	112.3	117	116	104
8	Left Back Panel	95.7	86	97	104
9	Right Front Fender	102.8	99	113	97
10	Right Front Door	116.6	112	126	112
11	Center Panel Right				
12	Right Rear Door	106.0	103	112	103
13	Right Back Panel	100.9	109	105	89

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : E	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Grime - Small / Mat Other - Missing - Yes / (R) Front Seat - Grime - Large / (R) Front Trim - Grime - Large / (R) Rear Trim - Grime - Large / Rear Seat - Grime - Large / (L) Rear Trim - Grime - Large / (L) Front Trim - Grime - Large / (L) Front Seat - Grime - Large / Overall Interior - Smell - Yes / Overall Interior - Animal Hair - Yes / (L) Front Seat belt - Grime - Small / (R) Front Seat belt - Grime - Small / Ceiling - Grime - Medium	Remarks Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch - Large / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Mirror - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : E
Remarks Defects not found	Remarks Retractable Mirror - Issue - Yes / Warning Lamps - Issue - Yes / Panel, Meter - Issue - Yes / Power Window (each) - Stuck, Gap - Yes / Door Lock - Issue - Yes / Power Seat - Issue - Yes / Power Steering - Issue - Yes / Shift Shock - Function - Weak / Air Conditioner - Function - Weak / Power Steering Pump - Leak - Yes / Radiator Water Pump - Leak - Yes / Battery - Weak - Yes / Remote Key & Smart entry - Issue - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Parking Brake - Function - Weak / Brake Pedal - Function - Weak / Turn Signal, Hazard Flasher - Issue - Yes / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Horn - Issue - Yes

Inspector Notes

Possible flooded. Towed unit. Mileage cannot be determined. Functions cannot be determined. Visible hairline scratches. Without seatcover, warranty booklet, LTO plate and front Plate number, tools, jack. With spare tire and 2keys.