

General Information

Date & Time: 16, Jun, 2026 16:52

Make	Toyota	Model	Wigo
YOM	2026	Odo Meter Reading	6,464
Registration No.	GBL1295	Chassis No.	MHKAA1BC8SJ046399
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	126.6	126	122	132
2	Boot Lid	104.6	104	105	105
3	Roof	95.3	94	81	109/98
4	Left Front Fender	104.6	100	112	102
5	Left Front Door	108.3	103	105	117
6	Center Panel Left				
7	Left Rear Door	107.6	112	111	100
8	Left Back Panel	107.3	105	106	111
9	Right Front Fender	105.6	110	105	102
10	Right Front Door	103.2	111	102	97
11	Center Panel Right				
12	Right Rear Door	107.8	97	105	122
13	Right Back Panel	98.3	100	99	97

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Small / (R) Front Trim - Grime - Minimal / (R) Rear Trim - Grime - Minimal / (R) Front Floor Mat - Grime - Minimal / Rear Seat - Grime - Small / (L) Front Seat - Grime - Small / (L) Rear Trim - Grime - Small / (L) Front Trim - Grime - Small / Overall Interior - Animal Hair - Yes / Ceiling - Grime - Small / (L) Front Floor Mat - Grime - Minimal / Mat Other - Grime - Minimal	Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch - Large / (R) Rear Fender, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch - Large / (L) Mirror - Scratch - Minimal / (R) Mirror - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

Audio Radio and Back Camera cannot fully function due to password lock. Visible hairline scratches. Incomplete tools. Without warranty booklet. With jack, sparetire, seatcover, LTO plate and 1key.